

NOTE: The Wedge Mounts in the Center of the Rear Overhead Cross Bar above your head

Part #7035 & 7045

- 1) Install horseshow brackets around the Overhead Cross bar above your head using the #10-32 Screws and washers included mount the Speaker Wedge into the inserts. (Fig.1)
- 2) After the brackets are installed the Wedge will rotate loosely around the bar. **Position to the desired angle. (Fig. 2)**
- 3) Once the wedge is positioned drill 13/64" Hole through bracket hole into the Center Bar. (Fig. 3)
- 4) Using the self-taping screw mount the wedge at your desired angel and screw into place. (Fig. 4)
- 4) Connect the 10' wire harness to the back of the Wedge
- 5) Run Wire harness to desired location.




(Fig. 1)



(Fig. 2)



(Fig. 3)



(Fig. 4)



Close Up Installed on a Ranger



Front View Installed

WIRING GUIDELINES

FOR #7035 & #7045

- 1) Connecting Speakers:
Splice wires from the Wedge into the left and right speaker wires under the dash
- | | |
|----------------------------|-------------------------------|
| Drivers Side - Left | Passenger Side - Right |
| Green / Red (+) | White /Red (+) |
| Green (-) | White (-) |

FOR 7045 with LED Light Show

NOTE: Not used for #7035 W/O LED Light Show

- 2) Connecting the Power for the LED Light Show
- LED Light Show**
Red (+) Attach to Battery or Fuse
Black(-) Attach to a good ground

RANGER Brackets & Screws



Part #71XXB (Fits 1.75" Bar)